

Renewal of certificate under the Boilers Act, 1923

Procedure:

All the Registered Boilers are to be inspected and their certificates are to be renewed as per Sec 8 of the Boilers Act, 1923.

The owner of the Boiler has to make the necessary Annual Inspection fees in Rupees based on the Heating Surface area of the boiler as given below: -

For fees details refer the **Notification - G.S.R.664 (E) - Central Boilers Board - Dt.26th August 2015.** Which is available in Notifications page.

After making the necessary fees payment, the owner of the Boiler has to furnish the following detail to the officer concern of their area for one of particulars visit to [www.boilers.tn.gov.in/contact us.html](http://www.boilers.tn.gov.in/contact-us.html).

Boiler Registry No. :

Heating Surface Area of the Boiler in m² :

Fees payment details :

Proof of Fees payment : To be enclosed.

Date of readiness for Boiler inspection :

Duties of the owner for preparing of the Boiler for Inspection.

PREPERATION FOR EXAMINATION

The Boiler to be inspected should be effectively isolated from steam line and other connected Boiler if any

Boiler should be thoroughly cleaned internally and externally

All the Inspection doors namely manhole, Mud hole, Peep holes etc., are to be kept open and proper arrangements to be made for easy access for carrying out the inspection through the above inspection doors.

Mountings and fittings namely safety valve, water columns, pressure gauges and similar accessories if any are to be effectively isolated from the Boiler.

Proper lighting and ventilation should be ensured.

For detailed procedure, please refer Regulation 390 of Indian Boiler Regulation, 1950 (visit to dipp.nic.in/boiler_rules_updated/index1.htm).